





East 17th Street



EXPLANATION

-  **MW-9** Groundwater Monitoring Wells Installed by MJA Consulting, Inc.
-  **B-11** Location and Designation of Soil Boring by MJA Consulting, Inc.
-  **VE-10** Location and Designation of Vapor Extraction Wells.
-  **AS-8** Location and Designation of Air Sparging Wells.
-  **D** Location and Designation of Soil Borings by CJA & Associates (1/28/02).
-  **CB-5** Location and Designation of Confirmation Soil Borings

-  **(1,200)** Benzene Concentration in Groundwater in Micrograms Per Liter ($\mu\text{g/l}$).
-  **1,000** Contour of Benzene Concentration in Micrograms Per Liter ($\mu\text{g/l}$). Dashed Where Inferred.



CJA C. JAMES & ASSOCIATES, INC.
Environmental Consultants

Client:
BEACON BAY AUTO WASH NO.3
OCHCA Case #90UT99
481 East 17th Street, Costa Mesa, California

SITE PLAN WITH BENZENE CONCENTRATIONS IN GROUNDWATER ON JULY 27, 2005

Plate 5

Drawn By: H.L. Approved By: H.H. Project Number: 00445 Date: July 2005